



Application Instructions for Fabric Coating

1. Vacuum the surface
2. Clean any spots with a mild cleaner
3. Before you apply coating, test it on a small surface to avoid discoloration.
4. Spray the product enough so the surface is slightly damp. No need to wipe the surface after coating is applied
5. Allow drying time of at least 6 hours

Application Video: https://www.youtube.com/watch?v=Z1s4_dsUSnU